

STATE OF ISRAEL
MINISTRY OF TRANSPORT
CIVIL AVIATION ADMINISTRATION

AD No. 95-28
Date: 10 May 1995

AIRWORTHINESS DIRECTIVE

This Airworthiness Directive, issued by the Civil Aviation Administration in accordance with the Israeli Aviation Regulations, applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

APPLIES TO: Israel Aircraft Industries Ltd. (IAI), models 1123, 1124 and 1124A all serial numbers.

SUBJECT: Inspection of aileron push-pull tube and guide rollers.

REASON: Excessive wear discovered on aileron push-pull tube P/N 513512-1 in area of guide rollers.

ACTION: Inspect guide rollers and push-pull tube for free rotation and wear and rectify as required per the following IAI Service Bulletins, revision new or later CAAI approved revision:
1123-27-043 for model 1123 airplanes
1124-27-129 for models 1124 and 1124A airplanes.

COMPLIANCE: Within the next 50 flight hours after the effective date of this AD and thereafter at each 600 hours inspection.

EFFECTIVE DATE: 24 May 1995.

FOR FURTHER INFORMATION CONTACT: Mr. J. Gideoni, Engineering and Manufacturing Branch, P.O.Box 8, Ben-Gurion Airport, Israel, Tel. 972-3-9712415, FAX. 972-3-9721636.