

**State of Israel
Ministry of Transport
Civil Aviation Administration**

AD No. 30-00-07-10

Date: July 12, 2000

AIRWORTHINESS DIRECTIVE

This Airworthiness Directive, issued by the Civil Aviation Administration in accordance with the Israeli Aviation Regulations, applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

- APPLIES TO:** The following Israel Aircraft Industries airplane Models and serial numbers, certificated in any category:
Model **1123**, all serial numbers
Models **1124, 1124A**, all serial numbers
Model **1125**, serial numbers 004 thru 029, except serial number 020
- SUBJECT:** Windshield Wiper Arm Inspection.
- REASON:** To prevent loss of rain removal capability due to windshield wiper arm rivet failure and subsequent separation of the wiper arm tip assembly in flight.
- ACTION:** Inspect the windshield wipers and replace the wiper arm tips, if required, as detailed in the following Alert Service Bulletins:
Model 1123: **1123-WESTWIND** S.B. No. 1123-30A-050
Models 1124, 1124A: **1124-WESTWIND** S.B. No. 1124-30A-142
Model 1125: **ASTRA** S.B. No. 1125-30A-222
- COMPLIANCE:** Unless already accomplished, compliance with this AD is required within 10 flight hours after the effective date, for aircraft having more than 4000 flight hours. For aircraft having less than 4000 flight hours, compliance is required within 3 months after the effective date of this AD.
Wiper units failing the inspection criteria, must be repaired or replaced prior to returning the aircraft to service.

EFFECTIVE DATE: July 30, 2000.

FOR FURTHER INFORMATION CONTACT: Mr. N. Kletshevsky, Engineering and Manufacturing Branch, CAAI - P.O.Box 8, Ben-Gurion Airport, Israel 70150.
Telephone: 972-3-9774-539, Fax: 972-3-9774-592.