

**State of Israel
Ministry of Transport
Civil Aviation Authority**

Ref. ShareDoc No. 06890217

AD ISR-I-52-2017-03-29

Date: 01.03.2017

AIRWORTHINESS DIRECTIVE

This Airworthiness Directive, issued by the Civil Aviation Authority in accordance with the Israeli Air Navigation Regulations applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

- APPLIES TO:** GALP model G100, 1125 Westwind Astra, Astra SPX aircraft serial numbers 004 and 011 through 158 certificated in any category.
- SUBJECT:** Adjustment of the Main Entrance Door (MED) Closed and Locked Indication microswitch.
- REASON:** To improve the Main Entrance Door (MED) microswitch adjustment procedure so that the locking indication will be extinguished when the door handle is locked.
- ACTION:** Accomplish an updated rigging procedure for adjustment of the Main Entrance Door microswitch per Gulfstream Service Bulletin No. 100-52-312 or later approved revision .
- COMPLIANCE:** Unless already accomplished, comply with this AD at the next suitable planned maintenance inspection within the next 12 months from the effective date of this AD.

EFFECTIVE DATE: March 30, 2017.

FOR FURTHER INFORMATION CONTACT: Mr.Saul Pascal, Engineering Branch, CAAI - P.O.Box 1101, 3 Golan Street, Airport City, Israel, 70151 Telephone: 972-3-9774583, Fax: 972-3-9774592, E-mail: pascals@mot.gov.il