

STATE OF ISRAEL
MINISTRY OF TRANSPORT
CIVIL AVIATION ADMINISTRATION

AD No. 29-97-03-10
Date: 27 March 1997

AIRWORTHINESS DIRECTIVE

This Airworthiness Directive, issued by the Civil Aviation Administration in accordance with the Israeli Aviation Regulations, applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

APPLIES TO: Israel Aircraft Industries Ltd. (IAI), models 1121/1121A/1121B/1123/1124/1124A Jet Commander, Commodore Jet and Westwind aircraft, all serial numbers; models 1125 Astra and ASTRA SPX, serial numbers 004 thru 080.

SUBJECT: Hydraulic Power - Hydraulic Fuses Functional Test and Replacement.

REASON: To verify proper operation of the hydraulic fuses and introduce an improved fuse type, less susceptible to corrosion.

ACTION: Inspect the Hydraulic Fuses installed in the brake system and in the emergency hydraulic indicating system as detailed in the following Service Bulletins:
1121-29-022 for models 1121/1121A/1121B
1123-29-045 For model 1123
1124-29-132 for models 1124/1124A
1125-29-154 for models 1125 and ASTRA SPX

COMPLIANCE: Unless already accomplished in accordance with one of the Service Bulletins listed above, perform a functional check within the next 250 flight hours or one year, whichever comes first, from the effective date of this Airworthiness Directive.

Thereafter, perform periodical checks per Maintenance Manual/Continued Airworthiness Instructions, or per the applicable Service Bulletin.

The periodic check interval specified in the Maintenance Manuals/Continued Airworthiness Instructions revised September 1996 or later revision, takes precedence over the interval specified in the Service Bulletins.

EFFECTIVE DATE: April 10, 1997.

FOR FURTHER INFORMATION CONTACT: Mr. N. Kletshevsky,
Engineering and Manufacturing Branch, P.O.Box 8, Ben-Gurion
Airport, Israel, Tel. 972-3-9773758, FAX. 972-3-9721636.