

**State of Israel
Ministry of Transport
Civil Aviation Administration**

**AD 32-04-09-08
Date: November 24, 2004**

עדיין בהכנה!!!

AIRWORTHINESS DIRECTIVE

This Airworthiness Directive, issued by the Civil Aviation Administration in accordance with the Israeli Aviation Regulations, applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

APPLIES TO: Gulfstream Aerospace LP (GALP) Models 1125 ASTRA, ASTRA SPX and G100 aircraft serial numbers 004 - 145 certificated in any category.

SUBJECT: Main Landing Gear – Ground contact switch – Changing the installation direction of the mounting bolts .

REASON: To remove

ACTION: Unless previously accomplished, perform the correct mounting of the 2 bolts in according Gulfstream S/B No. 100-32A-275R1

COMPLIANCE: Compliance with this AD is required within 250 flight hours .

EFFECTIVE DATE: December 15 , 2004 .

FOR FURTHER INFORMATION CONTACT: Mr. N. Kletshevsky, Engineering and Manufacturing Branch, CAAI - P.O.Box 8, Ben-Gurion Airport, Israel 70150.
Telephone: 972-3-9774-539, Fax: 972-3-9774-592, e-mail: kletsbn@mot.gov.il.